Map ID MAP FINDINGS

Direction Distance

Distance EDR ID Number
Elevation Site EDR ID Number
EDR ID Number

942 SPILL NUMBER 0209428 NY Spills S106010036
East 3049 BRIGHTON 14 ST N/A

> 1 1.257 mi. 6639 ft. BROOKLYN, NY

 Relative:
 SPILLS:

 Higher
 Name:
 SPILL NUMBER 0209428

 Actual:
 Address:
 3049 BRIGHTON 14 ST

 10 ft.
 City,State,Zip:
 BROOKLYN, NY

Spill Number/Closed Date: 0209428 / 2003-11-13

Facility ID: 0209428 Facility Type: ER DER Facility ID: 123980 Site ID: 145507 DEC Region: 2 Spill Cause: Other Spill Class: В1 2401 SWIS: Spill Date: 2002-12-13 Investigator: **JXZHAO** Referred To: Not reported Reported to Dept: 2002-12-13 CID: 396

Water Affected: Not reported Tank Truck Spill Source: Spill Notifier: Citizen Cleanup Ceased: Not reported Cleanup Meets Std: False Last Inspection: Not reported Recommended Penalty: False **UST Trust:** False Remediation Phase: 0 Date Entered In Computer: 2002-12-13

Spiller Address: 2002-12-13

Spiller Address: 2125 MILL AVE

Spiller Company: 001
Contact Name: TRINH ENG

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

ZHAO DEC Sigona spoke to affected party (Eng) 3051 Brighton 14th Street on 12/13/2002 at 12:15 PM and confirmed spill from neighbor 3049 Brighton 14th Street fuel oil delivery. The spill occurred after Madison Oil pipe was dislogded and spill went down road to impact storm drain and adjoining residence. Vapors impacting the residence. DEC Sigona dispatched DEC Zhao to investiagte on 12/13/2002. DEC called Madison Fuel Oil and spoke to Susan Magi at 12:30 PM who will update DEC on status of cleanup, and will respond immediately. 2:30PM: Spill went on the shared driveway between the two properties and run to the storm drain at 3051 Brighten 14 Street backyard. Madison crew has cleaned the surface spills including windows, doors

and backyard garage area. There is no spills inside houses

(basement)."

Remarks: "Caller reports that oil co was making a delivery to next door

neighbor and that the hose came out of the fill pipe and spilled oil...oil co is still there. caller was looking for information on what needs to be done to clean up material. spill is in her driveway.req callback. rec'd call from oil co approx 100 gal spilled

they have some speedy dry down now and have a crew on the way...due

Map ID MAP FINDINGS
Direction

Distance Elevation Site

Database(s)

EDR ID Number EPA ID Number

to oil hose breaking."

All Materials:

Site ID: 145507 Operable Unit ID: 862528 Operable Unit: 01 Material ID: 516400 Material Code: 0001A Material Name: #2 fuel oil Case No.: Not reported Material FA: Petroleum 100.00 Quantity: Units: G Recovered: .00

Oxygenate: Not reported